

25X1A

25X1A

[] 2389-67
Copy 5 of 11

10 August 1967

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6710

25X1D 1. Subject mission critique was conducted in the OSA Control Center commencing at 1430 hours, 25 July 1967. Appropriate OSA, OSI and [] participated.

2. Mission Data:

- 25X1A
- a. Mission Number: BX6710
 - b. Date Flown: 20 July 67
 - c. Area of Operation: North Vietnam
 - d. Mission Success: Successful
 - e. Pilot Name: []
 - f. Aircraft Number: 129
 - g. Primary or Spare Flown: Primary
 - h. Takeoff Time - Planned: 20/0230Z
Actual: 20/0232Z
 - i. Landing Time - Planned: 20/0731Z
Actual: 20/0727Z
 - j. Time Enroute - Planned: 5:01
Actual: 4:55
 - k. Departure Base: Kadena
 - l. Landing Base: Kadena
 - m. Equipment: []

25X1D

25X1A

GROUP 1
Excluded from automatic
downgrading and
declassification

HANDLE VIA []
COMINT CONTROL
CHANNELS JOINTLY

25X1A

2389-67
Page 2

25X1A

3. Operations:

a. Route (INS plot vs planned): Satisfactory - within 1-2 miles of planned route throughout.

(1) INS Terminal Error: 4.5 NM

(2) INS Spec Error: 13.9 NM

b. Mission Generation & Operational Support: Satisfactory

c. Other Comments:

(1) Top off air refueling re-positioned 95 NM north of established position due weather. Refueling was completed at designated end A/R point.

(2) DTF recommends 10,000# minimum fuel reserve at this time for future missions.

4. Weather: Weather in top off refueling area deteriorated to unsatisfactory status.

a. Forecast vs Actual: Slightly worse than briefed.

b. Weather Scout Reporting: Satisfactory.

5. Intelligence:

a. Target Coverage:

(1) 28 of 48 North Vietnam COMOR targets covered.

(2) 80 SAM sites identified, 20 of which not covered on BX6709 (5 sites were occupied, 2 identified as new).

(3) 7 of 9 priority SSM targets in North Vietnam covered.

25X1A

HANDLE VIA
COMINT CONTROL
CHANNELS JOINTLY

OX CART/

TOP SECRET

Approved For Release 2002/06/14 : CIA-RDP69B004000100070005-3

25X1A

2389-67

Page 3

25X1A

b. Quality of Take:

(1) Resolution: One to one and one-half feet at NADIR. Some degradation due to haze.

(2) Camera Operation: Satisfactory, minor data chamber malfunction which did not present any significant problem.



d. Significant Findings:


(1) Two SAM sites (#25 & #56) shown as unoccupied on Mission BX6709 (19 July 67) shown to be occupied on this mission (20 July 67).

(2) Analysis of Haiphong hampered by haze/obliquity.



e. Take Movement:

(1) Camera: Satisfactory.



6. Materiel:

a. Aircraft General: Satisfactory

25X1A

HANDLE VIA



Approved For Release 2002/06/14 : CIA-RDP69B004000100070005-3

OXCAR/



TOP SECRET

COMINT CONTROL
CHANNELS JOINTLY 25X1A

25X1A

[] 2389-67
Page 4

25X1A

(1) FWD by pass door flight blinked on once during flight;
GRD checked OK and also OK on subsequent training flight.

b. Aircraft Systems: Satisfactory.

(1) TACAN failure occurred on recovery leg.

7. Communications:

a. Message Traffic: Satisfactory.

b. [] Satisfactory.

c. HF/UHF Communications: Satisfactory.

8. Significant Actions Taken:

a. Minimum fuel reserve established at 10,000# per Colonel
[] recommendation.

9. Outstanding Actions Required:

a. OSI/OEL to perform analysis of Sys VI take from this mission
on a priority basis.

b. OSI/OEL to present System VI analysis briefing as soon as
possible in coordination with Intelligence Division, OSA.

25X1A

for
[]
WILLIAM E. SHELTON
Colonel, USAF
Deputy for Operations, OSA

25X1A

HANDLE VIA []
COMINT CONTROL
CHANNELS JOINTLY

25X1A

25X1A

[] 2389-67
Page 5

25X1A

25X1A OXC/O/OSA/[] pm

Distribution:

- #1 - D/SA
- #2 - D/O/OSA
- #3 - D/M/OSA
- #4 - D/R&D/OSA
- #5 - OXC/O/OSA
- #6 - Intel/O/OSA
- #7 - Wea/O/OSA
- #8 - Commo/O/OSA
- #9 - ADP/O/OSA
- #10 - RB/OSA
- #11 - Chrono

25X1A

25X1A